How to Fix – Alarm 02

This procedure tells you how to fix Alarm 02:


-Symptom : Alarm 02 occurs

-Cause : The oil cooler's air filter and condenser need to be cleaned.

-Solution : (1) Release alarm and

(2) Clean air filter and condenser

Step 1. Press "ENT" button on the oil cooler for about three seconds to clear the alarm.



Step 2. Clean the air filter and the condenser before running the cooler.

Copyright 2018 by Kwangrim. No unauthorized reproduction. Last Published On June 01,2018